

GLOCK Slimline MOSK

Accompanying Sheet


www.glock.com



with cover plate



without cover plate/optic



with optic*



*not included

Parts



SCREWS

2 units ultra-low profile Hex, M3x6 screws to install the GLOCK cover plate.

Make sure to use only these screws at 0.5 Nm / 4.4 lbf. inch for attaching the cover plate.



SCREWDRIVER

1.5mm Hex end wrench

⚠ WARNING

Only fire the GLOCK MOSK pistol models with the GLOCK cover plate mounted or an optical sight installed.

NOTICE

The GLOCK 43X and 48 models with a MOSK configuration have slide cuts designed for specific micro-optics and do not include adapter plates. Please consult the manufacturer of your optic of choice for compatibility.

NOTICE


GLOCK recommends a periodic check of cover plate or optic screws to ensure tightness.

GLOCK MOSK Slimline pistol models



1


Complete the safety check and field strip steps as indicated in the GLOCK Instructions for use. Place the slide of your pistol on a flat surface making sure that the recoil spring guide ring overlaps the surface.



2

Remove the GLOCK cover plate.

Note: Make sure to use a drop of thread locker on the screws before reinstalling the cover plate.





3

To mount an optic on your slide, make sure to use a M3 screw provided in your optic package.

Warning:

If the screw protrudes more than **4 mm** from the bottom of the optic, it may cause damage to the weapon and/or cause malfunction.



4

Only shoot your GLOCK MOSK pistol with correctly installed GLOCK cover plate or optical system.



**WARNING: Cancer
and Reproductive Harm –
www.P65Warnings.ca.gov**